

Universal Service Repair Pigtails — Halogen Headlamp

1 Wire



5344-11 (1 PC)
Sealed Light
1/4" Make

BULB

H1, H3

2 Wire



5409-BP (1 PC)
Sealed Beam Headlamp
/ Flasher for Domestic &
Import Vehicles with 2
Prong Headlights
1957-97

OEM

LS145, PT270,
12101873, 88860447,
12101879, 12117334



5461-BP (1 PC)
18GA High Beam
Halogen Bulb Headlamp
1988-04

BULB

H10, 9005, 9145

OEM

PT168, 12101898,
1U2Z14S411FA



5462-BP (1 PC)
18GA Low Beam
Halogen Bulb
Headlamp
1988-03

BULB

9006

OEM

PT167, 12101897,
3U2Z14S411EUA,
5102409AA



5508-11 (1 PC)
Headlamp

BULB

H7



5509-11 (1 PC)
Headlamp

BULB

H8, H11

2 Wire



5510-11 (1 PC)
Headlamp

BULB

H880



5511-11 (1 PC)
Headlamp

BULB

H9



5512-11 (1 PC)

5512-36 (100 PC)
Sealed Light
19" Lead



5516-11 (1 PC)
Universal headlight
pigtail

BULB

H16

OEM

19168034



5517-11 (1 PC)
Universal H11B to
H11 adapter pigtail

BULB

H11



5518-11 (1 PC)
A/C Clutch Coil
Connector
1997-2017

OEM

WPT-273, WPT-1448,
88953306, 88952831,
3U2Z-14S411-GVA,
88953306, PT1521

3 Wire



5356-BP (1 PC)
Dimmer Switch
1965-81

OEM

PT1949, 88860504,
LS21



5365-BP (1 PC)
16GA Sealed Beam
Fiber Optic Lamp
Domestic & Imports

OEM

LS144, 88860446,
12117333, 12117367,
8965810, 937131,
S825, S866

3 Wire



5370-11 (1 PC)
Heavy Duty / Thermal /
Electronic Flasher
Cars, Trucks, Tractors,
Trailers & Industrial
Applications

OEM

5803



5407-BP (1 PC)

5407-35 (25 PC)
Sealed Beam / Flasher
2 or 3 Terminal

BULB

H4, 9003

OEM

PT500, 12117367



5435-BP (1 PC)
18GA Manual AC /
Horn Relay
1957-95

OEM

PT549, PT2068,
2962510, 12125637,
89057721



5460-BP (1 PC)
18GA Halogen Bulb
Headlamp
GM, Ford, Chrysler

BULB

9004, 9007

OEM

4400395, 4414332,
4430976, 4439076,
PT433, 12117260,
1U2Z14S411JA,
88988457,
XF5Z14S411AA



5507-11 (1 PC)
Sealed Beam
Headlamp

BULB

H4, 9003



5513-11 (1 PC)
Headlamp

BULB

H13, 9008

OEM

3U2Z14S411FKAA,
5U2Z14S411XA,
68018959AA, 998509