

Chrysler Socket Assemblies

1 Wire



5353-11 (1 PC)
Socket / Board / Tail
1996-04

BULB

3157

OEM

4676589, 88860570

2 Wire



5355-11 (1 PC)
Side Marker Light
Socket
2002-2019

OEM

55156027AA,
68032739AA,
55156027AB,
68046629AA



5414-BP (1 PC)
Front & Rear Side Marker
1979-98

BULB

67, 158, 194, 194A

OEM

3588314, 3588650,
4450821, 4400147,
88860426,
E1ZZ15A434A,
E25Y13410B,
E83Z13412C,
F2DZ13412B,
F2ZZ13412B



5416-BP (1 PC)
Front & Rear Side Marker
1972-87

BULB

67, 158, 194, 194A

OEM

3513686, 4055028,
4400588, 3738020,
4274041, 88860586

2 Wire



5463-BP (1 PC)
Front / Rear
Cornering & Side Marker
Lamp
1974-75, 1979-92

BULB

87, 93, 1073, 1141, 1156

OEM

3764865, 3764561,
3764863, 4124721,
4400216, 88860433



5465-BP (1 PC)
Backup / Cornering /
Turn Lamp
1991-97

BULB

2456, 3156

OEM

4400448, 4400741,
4636358, 19138475,
88860569



5468-BP (1 PC)
License Plate Lamp
1989-92

BULB

194

OEM

4414184, 88860460



5469-BP (1 PC)
Rear Turn / Stop / Tail
Double Contact

OEM

4450815, 2822196,
4864259, 88860587

3 Wire



5464-BP (1 PC)
Stop / Tail / Turn Lamp
1975-83

BULB

1157

OEM

3513558, 3747831,
3764561, 3764863,
3843431, 88860436,
8983501000

3 Wire



5466-BP (1 PC)
Park / Side Marker /
Stop / Tail / Turn Lamp
1975-92

BULB

198, 1016, 1034, 1154,
1157

OEM

3843432, 3843245,
4163003, 4362469,
88860435



5467-11 (1 PC)
Stop / Tail / Turn / Park
/ Marker
1990-2010

BULB

3157

OEM

4399900, LS171,
68060366AA,
88860572



5489-11 (1 PC)
Rear Turn / Stop / Tail
1980-84, 1989

OEM

4124081, 4274800,
4399576, 4399579,
88860482



5495-11 (1 PC)
1986-89

BULB

3057, 3157, 3357,
4157, 4114K

OEM

4368264, 4400740,
4450799, 4636359,
4773905, 88860450,
88860573

GM Service Repair Pigtails Metri Pack pigtails located on page 66

1 Wire



5640-BP (1 PC)
18GA Radiator Fan
Temperature Switch
Special multiple lock,
multi-seal connector.
1982-02

OEM

PT308, 12051234,
12102621, 12126456,
12146549, SSPTL

1 Wire



5650-BP (1 PC)
18GA Carburetor
Choke Heater
1982-96

OEM

PT1920, 88860475

1 Wire



5651-BP (1 PC)
18GA Electric Choke /
Truck Release Switch
GM without Fuel
Injection
1987+

OEM

PT102, 12085480,
12004035

