



# PICO®

## 3469-0, 3469-5 Specifications Sheet



### Instructions

1. Clean working surface of any dust and debris.
2. Cut away the required length from the roll. Peel away the protective film.
3. Begin the wrap with one complete overlap onto itself.
4. Stretch and layer the tape according to the pressure of the job, remember that the tape can stretch upwards of 400%, and that the more stretch layers onto of itself the stronger it will be.
5. the final layer needs to be wrapped onto itself.

Note: Repositioning tape after 2 minutes is not recommended, since it begins to bond immediately tape bonds completely in 24 hours.

### Specifications

Temperature Range	-50C - 260C
Thickness (mm)	0.5
Elongation	400%
Tensile Strength (Mpa)	7.8
Dielectric Strength (KV/mm)	26KV
Dimensions	1.0"W x 10'L

