

## Ford Socket Assemblies

### 2 Wire



**5455-BP** (1 PC)  
Park / Stop / Tail / Turn  
11/16" Mount Hole

**BULB**

198, 1016, 1034, 1154,  
1157

**OEM**

LS126, 88860428,  
D4AZ13412A,  
F02Z13K371B,  
F32Z13K371D,  
F42Z13K371D



**5483-11** (1 PC)  
Backup  
Trucks & Bronco  
1980-90

**BULB**

1156

**OEM**

LS151, 88860468,  
E0MY15536A,  
E1BB15A536BA,  
E1DZ15536A

### 3 Wire



**5449-11** (1 PC)  
Front Turn / Park &  
Rear Stop / Park / Turn  
Use with PICO No.  
5484  
1996-04

**BULB**

3157

**OEM**

F1TZ-13411A,  
88860592



**5451-BP** (1 PC)  
Park / Stop / Tail / Turn  
Cars 1973-80

**BULB**

1157

**OEM**

D2FZ-13410A,  
D3AZ-13410B, D5DZ,  
D5VY-13410A,  
3588427, 3588883,  
3690736, 3764123,  
8124663, 88860531,  
D2AB-14A553HA,  
J3690736, J8124663



**5452-BP** (1 PC)  
Park / Stop / Tail / Turn  
1973-79

**BULB**

1157

**OEM**

D3AZ-13410D,  
D4OZ-13234A,  
D40Z-13410A,  
D2AB-14A553FA,  
D4SZ13410A  
88860525,



**5453-11** (1 PC)  
Side Marker / Stop /  
Tail / Turn  
Use with PICO No.  
5485  
1996-2005

**BULB**

3057, 3157, 3357,  
4157, 4114K

**OEM**

F47Z-13411,  
88861082

### 3 Wire



**5456-11** (1 PC)  
Park / Turn  
Use with PICO No.  
5485  
1993-03

**BULB**

3057, 3157, 3357,  
4157, 4114K

**OEM**

F3LY-13411, 88861081



**5459-11** (1 PC)  
Side Marker Light  
Socket  
1992-2015

**OEM**

645550,  
F81Z-13411AA, HP3995



**5470-BP** (1 PC)  
Front Turn / Park  
1974-80

**BULB**

1157

**OEM**

D4OZ-13234A,  
D7FZ-13234A,  
D7FZ-13234B,  
D7FZ-13234D,  
88860443,  
D4OB13234AA,



**5471-BP** (1 PC)  
Park / Turn  
1974-76

**BULB**

1157

**OEM**

D3MY-13410A,  
D4DZ-13234A,  
D54Y-13234A,  
88860440,  
D2AB14A553BA



**5472-BP** (1 PC)  
Front Turn / Park  
1974-77  
HD Trucks  
1989-92

**BULB**

1157

**OEM**

D4ZZ-13234A,  
88860444,  
D4ZB-13234AA



**5475-BP** (1 PC)  
Stop / Tail / Turn  
Lincoln 1973-79  
Mercury 1975-78

**BULB**

1157

**OEM**

D4LY-13410A



**5477-BP** (1 PC)  
Park / Turn  
1973-92

**BULB**

1157

**OEM**

D1FZ-13234A,  
D5UZ-13410A,  
D7FZ-13234C,  
88860442

### 3 Wire



**5478-BP** (1 PC)  
Rear Turn / Stop / Tail  
1970-90

**BULB**

1157

**OEM**

D7OZ-13410A,  
E1FZ-13234A,  
E2VY-13410A,  
E25Y-13410A,  
88860445,  
D7OB13410AA,  
D7OZ13410A,



**5479-BP** (1 PC)  
Marker / Park / Stop /  
Tail / Turn  
1983-95

**BULB**

Wedge Bulb 2458,  
3057, 3157

**OEM**

3U2Z14S411JKA,  
88860458, E2D-  
Z13410A, E8P-  
Z13411A, E8PZ13411B,  
E8PZ13411C,  
F24Y13410A,  
F2AZ13234A,  
F2DZ13410A,  
F2MY13234A



**5786-11** (1 PC)  
Stop-Park-Turn  
Use with PICO No.  
5484  
1991+

**BULB**

3157

**OEM**

F1TZ-13411-F, LS92,  
88860591